


DIN 917

Sechskant-Hutmutter niedrige Form



d	h	t	s
M 3	5	3,4	5,5
M 4	5,5	4,4	7
M 5	7	5,2	8
M 6	9	7	10
M 8	12	9,5	13
M 10	14	11	17
M 12	16	13,5	19
M 14	18	15	22
M 16	20	17	24
M 18	22	19	27
M 20	25	21	30
M 22	28	22	32
M 24	30	24	36
M 27	32	26	41
M 30	34	28	46